

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION JACKSON ENVIRONMENTAL FIELD OFFICE 1625 HOLLYWOOD DRIVE

JACKSON, TENNESSEE 38305-4316
PHONE (731) 512-1300 STATEWIDE 1-888-891-8332 FAX (731) 661-6283

**December 23, 2014** 

Julie Duncan, Sustainability Officer ABB Inc. 1133 South Cavalier Drive Alamo, Tennessee 38001-3813

REF: Compliance Evaluation Inspection
Tennessee Stormwater Multi-sector General Permit
TNR051468
Crockett County

Dear Ms. Duncan,

On Thursday, December 18, 2014, I visited with you for the purpose of conducting a Compliance Evaluation Inspection (CEI) to determine your facility's compliance status related to the State's Tennessee Stormwater Multi-sector General Permit (TMSP), specifically for your site, permit number TNR051468.

My findings during this inspection were essentially a mirror image of my March 3, 2010, compliance inspection.

The following is an overview summary of this inspection:

- 1. As in 2010, ABB's SWPPP was found to be a very well written document and properly executed should provide continued TMSP compliance in the future for ABB, Inc.
- 2. It was noted that all quarterly visual inspections had been completed during the 2013 sampling year. Surprisingly to this inspector, only the fourth quarter of 2014 had been conducted during the 2014 sampling year.
- 3. Detailed inspections are currently conducted twice weekly of all site facilities that would impact stormwater quality and ABB's SPCC plan. These twice weekly forms do not fit the typical layout of what is considered an "Annual Comprehensive Inspection" form but this inspector is of the opinion that ABB is exceeding the intent of the Annual Comprehensive Inspection format and any one inspection can be considered an "Annual Comprehensive" inspection. Based on this observation, credit is given for meeting the "Annual Comprehensive" inspection requirement of the permit.

- 4. Stormwater training was found to be conducted twice a year, double the permit requirement. This practice is to be commended.
- 5. A drain inlet directly east of the east loading dock was found to be filled with a sandy looking material to the point that the direction of flow could not be visually determined. A review of the SWPPP indicates this to be a direct violation of Section 8.1 of your SWPPP.
- 6. The fact that ABB, Inc. has two stormwater control swales was noted in the March 3, 2010, CEI letter. Since that is still true, it merits mentioning again. These swales allow for visual observations of the water quality prior to release. This is an excellent Best Management Practice (BMP) and worth noting again.

#### **ACTION ITEMS:**

- 1. Please address and clean-out the one drain inlet noted in this inspection letter. Should there be other inlets that are un-noted, please check and maintain as required by ABB's SWPPP.
- 2. Please take whatever steps that are needed to make sure that the required "Quarterly Visual" samples are faithfully completed, documented and the inspection forms are available for future inspections.

Overall, ABB, Inc. has a very good stormwater program and it is the desire of the State's Division of Water Resources that ABB, Inc. will continue to exceed the minimum requirements of the TMSP Permit.

I appreciate the courtesy shown to me during this inspection. If you have any questions concerning my visit, this letter or any other issue that you think I could assist you with, fell free to contact me by phone at 731.512.1362 or by email at James.W.Scott@tn.gov.

Sincerely,

James W. Scott

**Division of Water Resources** 

**Jackson Environmental Field Office** 

731.512.1362

Cc Rodney Brooks, General Manager ABB, Inc. 1133 South Cavalier Drive Alamo, Tennessee 38001-3813



# TDEC - Division of Water Resources Jackson Field Office

## ICIS NPDES Facilities Inspection Report

					Fac	cility Data						
NPDES ID: TNR												
				Address	1128 Sou	uth Cavalier Drive,	Alamo, To	ennessee 3	8001-3813			
Permit Eff. Date: 07.08.2009 Pe				it Exp Date						Code: 3612		
	y Frank			Comp	liance M	onitoring Info	rmatio	n			To The said	
Compliance Moni	toring Activi	ity Name	Complian	nce Evaluat	ion (non-sa	mpling) (CEI)						
		* If	Bio Moni	toring is se	lected abov	ve, select the meth	nod used:					
Compliance Monitoring Activity Evaluation				n								
			H. K.	Compl	iance M	onitoring Date	es/Time	es				
intry Date/Time (	mm/dd/yyyy	/ hh:mm):	12/18/20	)14 8:50		Exit Date/Time	(mm/dd/	yyyy hh:mr	n): 12/18/2	014 10:00		
	"			- 19	Facility F	Representativ	es					
Julie Duncan, Sus	tainability C	Officer, 731.6	96.5361			Rodney Brooks/ F	Plant Mar	ager/ 731.6	596.5224			
On-Site Represen						Responsible Official(s), Title, Phone Number						
		0.407		Stati	ute and S	Section Inform	nation					
ederal Statute:	CWA - CI	ean Water A	∖ct			State Statute:	Tennes	see Water (	Quality Contro	l Act		
Programs:	NPDES- E	Base Prograi	m (Limits	, Reporting	, & Schedu	le)						
Complianc	e Monitori	ng Reason	Rando	om Inspec	tion							
Compliance Monitoring Agency Type: State						Ag	gency Nam	ne: TDEC - DWR				
Did EPA assist/ Inspection? No					Time Physically conducting activity: Days: 3				3	Hours:		
Inspection Type: State			Compliance Monitoring Action Outcome: No					No Violation	o Violation			
Lead Agency: State				Compliance Monitoring Rating Code: Satisfa					sfactory			
f Joint Inspection	, what was t	he purpose	of the ot	her party?								
		Areas Ev	/aluate	ed During	g Inspec	tion (Check or	nly thos	e areas e	valuated)			
Permit				⊠ Sel	Self - Compliance Program			Pretreatment				
Records / F	Records			Со	Compliance Schedule Po			Pollution Prevention				
Facility Site Review				☐ Lal	Laboratory			Storm Water				
Effluent / Receiving Waters				Operations & Maintenance			Combined Sewer Overflow					
Flow Meas	Flow Measurement			111-01	Sludge Handling / Disposal			Sanitary Sewer Overflow				
			VIEW FU	Com	oliance N	Monitoring Su	mmary					
014, only the 4th lan. (4) A drain in	Quarter Visu let due east	ual inspection of the east l	on was co oading o	ompleted a lock was fo	ind docume ound to be f	2) All of 2013 Quar ented. (3) Employe filled with a sandy evelop (Section 8.1	ees are tra looking r	iined 2 time	es a year on sto	orm water and	their SPCC	
	10	1	4	EPA	and Sta	te Representa	atives					
ames W. Division				vision of W	of Water Resources/ JEFO/ 731.512.1362				12/18/12014			
Inspector's Signature			Ag	Agency / Office / Phone			Date	Date				
Conner Dean bl-			Di	Division of Water Resources/ JEFO/ 731.512.1302			12/	19/14				
Manager's Signature			Ag	Agency / Office / Phone					0			

**TDEC** 

# TMSP-Industrial Storm Water Inspection Form

Water Pollution Control Division Jackson Field Office

FACILITY DATA										
NAME OF FACILITY INSPECTED		INSPECTION DATE		11	TIME ENTRY / TIME EXIT		TMSP TRACKING NUMBER			
ABB Power T & D		12.18.2014		0	0850/1000		TNR051468			
LOCATION OF FACILITY			MAILING A	ADDRESS OF FACIL	ITY		EFFECTIVE DATE		EXPIRATION DATE	
1128 South Cavalier				SAM	E		07.08		05.14.2014	
Alamo, TN 38001-38										
FACILITY CONTACT/TITLE / PH		06 50	RESPONSIBLE OFFICIAL/ TITLE / PHONE							
Julie Duncan/Sustair	nability Officer/731.69	96.53	Rodney Brooks /General Manager/ 731					731.69	6.5224	
INDUSTRIAL ACTIVITY DESCRIPTION										
Power, Distribution, and Specialty Transformers										
			TITUDE:		LONGITUDE: SECTOR(S):					
SIC CODE(S)3612 3612		35.7792 -89.128094 AC								
WATERSHED:	RECEIVING STREAM:		1/-:  C::	1.						
8010205. (2016).			Kail Cro	еек						
Forked Deer-South										
Fork	TAKOL	TION 212.	TE LISTED:			MS4 DISCHARGE:				
303d LISTED: YES⊠ NO□	TMDL: S. YES N/A		YES NO		YES NO					
MONITORING AND REPORTING										
VISUAL EXAMS – ALL TMSP FACILITIES REQUIRED TO PERFORM										
PERFORMED:	(Had all 4 quarters of 2013, only the 4 <sup>th</sup> quarter of 2014) YES⊠ NO									
FREQUENCY:	*1/QTR							YES⊠ NO□		
STORM EVENT:	*0.1" @ 72 HRS & W/I 30 MINUTES YES NO									
OBSERVATIONS:	*DOCUMENTED YES⊠ NO							YES⊠ NO□		
RECORDS:	*KEEP W/I SWPPP YES NO							YES⊠ NO□		
ANALYTICAL MONITOR	RING REQUIRED: YES	] NO	$\boxtimes$		NONE REQUIRED			RED		
	NUMERICAL LIMIT mg/L Table:		FREQUENCY:		<u>CU</u>	CUT-OFF mg/L		FREQUENCY:		
PARAMETER					<u>Table:</u>			Annually		
				=						
SAMPLES COLLECTED:	(NA)							YES NO		
STORM EVENT:	*0.1" @ 72 HRS & W/I 30 MINUTES							YES NO		
SAMPLE TYPE:	MPLE TYPE: *GRAB							YES NO		
REPRESENTATIVE:								YES NO		
<b>EX. CUT-OFF LIMITS:</b> *NOTIFICATION OF EXCEEDANCE w/30 days & UPDATE SWPPP w/ 60 DAYS						YS	YES NO			

DECODDS:	*RETAINED FOR MINIMUM OF 3 \	/DC	NA		YES NO				
RECORDS:		1103.	NA NA						
REPORT SUBMITTED:	*PM NLT MARCH	101.1			YES NO				
TMSP-Industrial Storm Water Inspection Form (Continued)									
·									
FACILITY: ABB Pov	wer T & D TRACKING NO.	: TNR051468	DATE:	12.18.2014					
ANALYTICAL MONITORING (continued from Page 1)									
<u>SWPPP CONTENT</u>									
SWPPP PREPARED					YES⊠ NO□				
PP TEAM:					YES⊠ NO□				
SOURCES LIST:					YES⊠ NO□				
DRAINAGE MAP:					YES⊠ NO□				
EXPOSED MTLS.:					YES⊠ NO□				
SPILLS/LEAKS:					YES⊠ NO□				
MEAS. & CONTROLS:					YES⊠ NO□				
HOUSEKEEPING:					YES⊠ NO□				
PREV. MAIN.:					YES⊠ NO□				
SPCC:	(It is a separate document)				YES⊠ NO□				
INSPECTIONS:					YES⊠ NO□				
TRAINING:					YES⊠ NO□				
NON-SW CERT.:					YES⊠ NO□				
SED./EROS. CON.:	(They mainly use vegetation to	stabilize)			YES⊠ NO□				
RUNOFF MGMT.:					YES⊠ NO□				
UPDATED PLAN:					YES⊠ NO□				
COMP. SITE EVAL.	*1/YR				YES NO				
* DENOTES TMSP REQUIREMENT									
OBSERVATIONS & COMMENTS									
INDIVIDUAL(S) CONTACTED	OTHER DWPC PERS	SONNEL PR	ESENT:						
Julie Duncan									
WEATHER CONDITIONS:	Overcast/ Cool/ Wet	SAMPLES: YES	No⊠	PHOTOS TAKEN:	YES NO				

### **OBSERVATIONS & COMMENTS**

(Continued from Page 2)

FACILITY: ABB POWER T & D

TRACKING No.: TNR0051468

DATE:

12.18.2014

- 1. The facility is inspected in detail twice a week with documentations. NOTE: This form is so detailed that any one inspection sheet could serve as their Annual Comprehensive Inspection.
- 2. All of 2013 Quarterly Visual Inspections were completed and on file. During 2014, only the 4<sup>th</sup> Quarter Visual inspection was completed and documented.
- 3. Employees are trained 2 times a year on stormwater and SPCC.
- 4. A drain inlet due east of the east loading dock was found to be filled with a sandy looking material to the point that the direction of flow could not be determined. This is a violation of their SWPPP, Section 8.1.

NAME/TITLE AND SIGNATURE OF PRIMARY INSPECTOR

James W. Scott

AGENCY/DIVISION / OFFICE / PHONE AND FAX NUMBERS
TDEC / DWPC / JFO

(731) 512-1362 / (FAX) (731) 661-6283

DATE

12.18.2014